WELLS LAMONT

Industrial

## PRODUCT SPECIFICATION SHEET



# PRODUCT INFORMATION

Style: LN 13

 Size
 Part #
 Overedge

 Sizing:
 XXSmall
 135557
 Red

 XSmall
 135558
 Green

 Small
 135559
 Yellow

 Medium
 135560
 Blue

 Medium
 135560
 Blue

 Large
 135561
 White

 XLarge
 135562
 Orange

 XXLarge
 135721
 Black

Registered Brand Name: Whizard® Classification: Cut Resistant



#### PRODUCT DESCRIPTION

 Description:
 High Performance Cut Resistant Glove

 Color:
 Black and White (Gray) / Gray Cuff

Material: Combination of High Performance Fibers, Stainless Steel and Antimicrobial Fibers

CFR 21 - Approved for Food Contact

Sold by: Piece
Packaging (Inner Pack): 6 Pieces
Packaging (Case Pack): 120 Pieces

### **CUT PROTECTION PERFORMANCE INFORMATION**

Test Method: ASTM F1790-97
Test Results: 2640 grams / 5.81lbs.

ANSI Level 4

### ABRASION PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM D3884-05
Test Results: 3500 revs (cycles)

### WASHING INSTRUCTIONS

Always wash similar products of the same materials together. This will eliminate different material types from being effected by non-recommended chemicals. Rinse all gloves thoroughly in cold water to ensure the release of particles in the products. If pre-soaking use luke warm water to ensure good particle softening. Mild detergents or chemicals should be used to enhance the laundering process. All products should be laundered using a mild soap and detergent. Use a warm water wash with a temperature not to exceed 160°F (71°C). Wash time should not be longer than 15 to 20 minutes. Use a rinse cycle for the product in cold water. Repeat above as often as needed to ensure a thoroughly clean product. It is important to use a high extraction speed to thoroughly remove all excess moisture. Tumble dry glove in a temperature not higher than 150°F (67°C) for a time of 15 to 20 minutes; adjustments in dry time may increase depending on quantity and weight of the products. Temperatures should not exceed 150°F (67°C).

### **CAUTION**

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

Wells Lamont Industrial 6640 W Touhy Ave Niles IL 60714

Toll-Free 1.800.247.3295 Fax 1.847.470.1026 www.wellslamontindustrial.com

JC 5/14